





## Technische Daten

|                                                                 |                                             |                                                                                                         |
|-----------------------------------------------------------------|---------------------------------------------|---------------------------------------------------------------------------------------------------------|
| Axialluftdüse PS 01/A AF2<br>Air purge PS 01/A AF2              | max .Druck 0,5 bar<br>pressure 0,5 bar max. | Es wird empfohlen ein Überdruckventil zu verwenden.<br>It's recommended to use a pressure relief valve. |
| Quarz-Scheibenvorsatz PS 01/I AF2<br>Quartz window PS 01/IA AF2 |                                             |                                                                                                         |





- Headquarters
- Sales and Service Center
- Sales abroad



Keller HCW GmbH  
Infrared Temperature Solutions (ITS)  
Carl-Keller-Straße 2-10  
49479 Ibbenbüren-Laggenbeck  
Germany

[www.keller.de/its](http://www.keller.de/its)  
Tel. +49 (0) 5451 850  
Fax +49 (0) 5451 85412  
[its@keller.de](mailto:its@keller.de)

## Distributor



INOR Transmitter Oy  
Unikkotie 13  
FI-01300 Vantaa  
Puhelin +358 10 4217900  
Faksi +358 10 4217901  
[myynti@inor.fi](mailto:myynti@inor.fi)