





Technische Daten

Axialluftdüse PS 01/A AF2 Air purge PS 01/A AF2	max .Druck 0,5 bar pressure 0,5 bar max.	Es wird empfohlen ein Überdruckventil zu verwenden. It's recommended to use a pressure relief valve.
Quarz-Scheibenvorsatz PS 01/I AF2 Quartz window PS 01/IA AF2		





- Headquarters
- Sales and Service Center
- Sales abroad



Keller HCW GmbH
Infrared Temperature Solutions (ITS)
Carl-Keller-Straße 2-10
49479 Ibbenbüren-Laggenbeck
Germany

www.keller.de/its
Tel. +49 (0) 5451 850
Fax +49 (0) 5451 85412
its@keller.de

Distributor



INOR Transmitter Oy
Unikkotie 13
FI-01300 Vantaa
Puhelin +358 10 4217900
Faksi +358 10 4217901
myynti@inor.fi